






1A



1B



2.



Model	X	H
PNJ 50	500-510	1500
PNJ 60	600-610	1500
PNJ 70	700-710	1500
PNJ 80	800-810	1500
PNJ 90	900-910	1500
PNJ 100	1000-1010	1500